Baron mixer cleaning instructions

Please read carefully , 1 man should manage the mixer alone , 1 man to barrow , 1 man to clean tools and 1 man to spread.

Please remove and clean paddle complete by undoing the top bolt between every mix.

It is strongly recommended that during use, in between mixes, the mixer is cleaned to remove any excess resin and aggregate as by the time all of the required mixes have been carried out the resin may already have set on the machine, making cleaning more difficult task. By following the instructions below, this two minute job between mixes can save you hours of cleaning and help to protect your machine.

- The trap door should be left open between mixes as due to the quick curing nature of resin, this can become seized making the machine inoperable.
- Remove excess resin and aggregate mix using a sponge soaked in white spirit paying particular attention to the trap door, exit chute, mixing paddles and safety grilles.
- Wipe the mixer with a clean, dry cloth or paper towel and allow to dry before adding the next pack

End of Day/Project Cleaning

Remove all the excess resin and gravel mix from the pan, trap exit chute, top pan safety grille and trap chute exit grille using a sponge which has been soaked in white spirit.

Empty one 25kg bag of dry gravel into the mixer and add 1 litre of white spirit to the pan. Allow the gravel and spirit to mix in the machine for around 10 minutes. After the time has elapsed, empty the pan and dispose of the gravel responsibly.

Again, using a white spirit sponge, wipe down all areas of the mixer including uprights, paddles (which can be removed for easier cleaning), pan, safety grilles and bucket holder.

Any tough or hardened resin can be removed by scrubbing with a wire brush to remove the residue and the trapdoor area should be paid particular attention. The trapdoor should be opened several times to ensure free movement and should be left open during drying.

THERE WILL BE A £300 CLEANING CHARGE IF THESE INSTRUCTIONS ARE NOT FOLLOWED.